



Protective Clothing Must Be Worn

Product Images



Short Description

Protective Clothing Must Be Worn

Description

Mandatory Signs specify actions that are required to safeguard health and/or avoid injury. Mandatory signs provide specific instructions that MUST be carried out. These industrial and workplace safety signs are essential for promoting the wearing of PPE and abiding by safe

workplace procedures. Symbols (or pictograms) are depicted in white on a blue circular background. Sign wording, if necessary, is in black lettering on a white background.

Additional Information

Safety Sign Type	Mandatory

Product Options

Sign Size:	140mm x 120mm
	240mm x 180mm
	300mm x 225mm
	450mm x 300mm
	600mm x 450mm
Sign Material:	Colorbond Steel
	Flute
	Polypropylene
	Self Adhesive Vinyl

